

cye



BLAKELY SOKOLOFF TAYLOR & ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS

09,751,516.

TELEPHONE (408) 720-8300
FACSIMILE (408) 720-8383
BSTZ_MAIL@BSTZ.COM
WWW.BSTZ.COM

INTELLECTUAL PROPERTY LAW
SILICON VALLEY
1279 OAKMEAD PARKWAY
SUNNYVALE, CALIFORNIA 94085-4040

OTHER OFFICES
LOS ANGELES, CA
ORANGE COUNTY/COSTA MESA, CA
SAN JOSE, CA
DENVER, CO
PORTLAND/LAKE OSWEGO, OR
SEATTLE, WA

June 7, 2004

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Certificate
JUL 15 2004
of Correction

Re: **CERTIFICATE OF CORRECTION**
U. S. Letters Patent No. 6,731,843
Issued: May 4, 2004
For: **MULTI-LEVEL WAVEGUIDE**
Inventor: Murali
Our File No. 42390.P10309

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

Edwin H. Taylor
Reg. No. 25,129

EHT/tc
Enclosures

16 JUL 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,731,843
DATED : May 4, 2004
INVENTOR(S) : Murali

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 1, at lines 66-67, delete "core cladding" and insert --core/cladding--.

In column 2, at line 3, delete "bump metal" and insert --bump/metal--.

In column 2, at line 6, delete "laser hole" and insert --laser/hole--.

In column 2, at line 19, delete "bump metal" and insert --bump/metal--.

In column 2, at line 38, delete "core cladding" and insert --core/cladding--.

In column 3, at line 34, delete "dixoxide" and insert --dioxide--.

In column 5, at line 8, delete "layer" and insert --layers--.

In column 5, at line 63, delete "Alternatively" and insert --Alternately--.

In column 5, at line 66, delete "lapped planarized" and insert --lapped/planarized--.

In column 6, at line 16, insert --- at the end of the line.

In column 6, at line 49, delete "Alternatively" and insert --Alternately--.

In column 6, at line 52, delete "alternatively" and insert --alternately--.

In column 6, at line 60, delete "(VSCSEL)" and insert --(VCSEL)--.

In column 6, at line 63, delete "misalignement" and insert --misalignment--.

In column 7, at line 3, delete "pathways" and insert --pathway--.

In column 7, at line 5, delete "pathways" and insert --pathway--.

In column 7, at line 39, delete "core cladding" and insert --core/cladding--.

In column 7, at line 48, delete "waveguide" and insert --waveguides--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,731,843

Certificate of Correction (PTO Form 1050)-Amended

16 JUL 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,731,843
DATED : May 4, 2004
INVENTOR(S) : Murali

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 1, at lines 66-67, delete "core cladding" and insert
--core/cladding--.

In column 2, at line 3, delete "bump metal" and insert --bump/metal--.

In column 2, at line 6, delete "laser hole" and insert --laser/hole--.

In column 2, at line 19, delete "bump metal" and insert --bump/metal--.

In column 2, at line 38, delete "core cladding" and insert --core/cladding--.

In column 3, at line 34, delete "dioxide" and insert --dioxide--.

In column 5, at line 8, delete "layer" and insert --layers--.

In column 5, at line 63, delete "Alternatively" and insert --Alternately--.

In column 5, at line 66, delete "lapped planarized" and insert
--lapped/planarized--.

In column 6, at line 16, insert --- at the end of the line.

In column 6, at line 49, delete "Alternatively" and insert --Alternately--.

In column 6, at line 52, delete "alternatively" and insert --alternately--.

In column 6, at line 60, delete "(VSCSEL)" and insert --(VCSEL)--.

In column 6, at line 63, delete "misalignement" and insert --misalignment--.

In column 7, at line 3, delete "pathways" and insert --pathway--.

In column 7, at line 5, delete "pathways" and insert --pathway--.

In column 7, at line 39, delete "core cladding" and insert --core/cladding--.

In column 7, at line 48, delete "waveguide" and insert --waveguides--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,731,843

Certificate of Correction (PTO Form 1050)-Amended

16 JUL 2004